

Figure 7



LEGEND:
ESTIMATED EXTENT OF IMPACTED SOIL
EXISTING GRADE, 5 FEET INTERVAL

Figure 7
*Estimated Extent of
Soil Impacts Above Cleanup Goals
Curtis Park Village
Sacramento, California*

REM 02/09